

Radiation Protection

Where is Radiation used in the Trust?

Radiology Department

- Main department (NX and CCH)
- Nuclear Imaging



Deanesly Centre

- Medical Physics Department
- Radiotherapy
- Deanesly Ward

Heart and Lung Centre

- X-ray and fluoroscopy units

UECC

- X-ray and CT




Wards and Theatres

- Mobile X-Ray (NX & CCH)
- Nuclear imaging patients

Rheumatology

- Bone densitometry (NX & CCH)

If you see these signs this means work with radiation is being undertaken in that area - DO NOT ENTER unless authorised



Where to get advice and help

Radiation Protection Supervisor (RPS)

Wherever work with radiation is used in a department there must be a Radiation Protection Supervisor. If you need assistance in a department ask for the RPS.

Radiation Protection Adviser (RPA)

The Trust must by law use an RPA. These can be accessed by phoning Medical Physics, ext 5522.

If your work involves routinely working with radiation, whatever your profession, you must ensure you are fully trained and acquainted with your areas before undertaking work. Please contact your department manager/training supervisor for further information.

Trust Radiation Safety Policy HS05